



WIRING DIAGRAM 230V 50HZ
AF300-350INGR




SCHEDA 99SM

WIRING DIAGRAM 400V 50Hz (3-PHASE MOTORS)




WIRING DIAGRAM 230V 50HZ
AF220-250-275GR




(SCHEMATG028E)

WIRING DIAGRAM 230V 50HZ
 AF300-330GR
 AF300-330VS/VM



(SCHEMATG 485)

WIRING DIAGRAM 230V 50HZ
 AF350-370-380GR
 AF330-350-370-380VS/MM



SCHEDA 99SM